

1

11 JUN 1928

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl. Sc. "TAIFUN".

Report Lon.

No. 92731a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


When due

The class is subject to stem plating, etc., being repaired at the Owners' convenience.

The Hamburg Surveyors now forward a letter from the Owners stating that they do not desire to retain the classification with this Society and that the vessel is being classed with the Germanischer Lloyd.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...





8. 6. 28.



© 2020

Lloyd's Register
Foundation