

sp Fiume.

submitted the Newport Surveyors should inform
owners representative that before the classification
can be issued the two Cochran donkey boilers,
intended for the ships use, must be fitted on board
safety valves adjusted under the supervision of the
Surveyors.

The Surveyors should ascertain & forward to this
the particulars of the test marks stamped on
boiler & satisfy themselves that the boilers are
in good condition.

W.L. A.R.S.



© 2020


Lloyd's Register
Foundation

007553-007562-0100



$$\frac{7 \times 300 \times 1}{12}$$

Handwritten signature or initials



© 2020

Lloyd's Register
Foundation