

Lloyd's Register of Shipping.

FOUNDED 1760.

RE-CONSTITUTED 1834.

Certificate of Class

Steel Screw Motorship "Anne Louise" ex "Maythorn"
 Official Number ✓ Port of Registry Esbjerg
 Owners Dampskibsselsk. Phoenix A/S. (Hans Andersen, Manager)
 Builders, and where and when Built Geo. F. Davies & Sons Limited, Lauzon, P. 2, November 1946.

REGISTERED PARTICULARS.

Length <u>114.3</u> feet	Tonnage, Gross <u>522.15</u>
Breadth <u>27.1</u> feet	Ditto under Deck <u>481.44</u>
Depth <u>15.7</u> feet	Ditto Net <u>254.07</u>

This is to Certify that this Vessel has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 2nd November 1946.

in a good and efficient state, and fit to carry dry and perishable Cargoes, and has been **CLASSED** and entered in the **REGISTER BOOK** of this Society, with the Character **100A1** For coasting service between Anticosti Island and



Demerara including the West Indies

subject to Periodical Surveys as required by the Rules.

The class is assigned and maintained upon the understanding that the anchors on board will be submitted to the Statutory Tests when the present state of emergency has passed.

Part Electrically Welded.

THE FREEBOARDS FROM THE DECK LINE ARE AS FOLLOWS:—

Tropical <u>5</u> feet <u>9 1/4</u> inches (T).	Winter <u>✓</u> feet <u>✓</u> inches (WNA).
Summer <u>6</u> feet <u>0 1/4</u> inches (S).	North Atlantic <u>✓</u> feet <u>✓</u> inches (WNA).
Winter <u>6</u> feet <u>3 1/4</u> inches (W).	Allowance for fresh water for all freeboards <u>3</u> inches

Witness my hand,

P. Blument

Secretary,

R. G. Smith
Chairman.

71, Fenchurch Street, LONDON, 7th April 1948

N.B.—If the vessel herein named proceed to sea with a less freeboard than that assigned, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

D/S 435



© 2020

Lloyd's Register
Foundation

007553-007562-0173