

ved by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

23 SEP 1941

SEL'S NAME.....TAMAHOKO MARU.....Rpt.....Kob.....No. 11849

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The KOBE Surveyors report (6.41)  
the vessel placed in dry dock and the bottom coated.

The 2nd S.S. No. 1, due 8.41, held  
and considerable renewals and repairs effected to shell  
and deck plating.

Minor repairs effected.

It is submitted the vessel  
appears worthy to remain as classed with record of survey  
6.41 and notation of S.S. No. 1-41.

100A1  
Shelter dk  
with fbd  
6.41 Kob  
S.S. Kob No. 1-41.

6.41  
22-9-41

PLATING to be DRILLED when  
vessel is 24 years old,  
or at next Special Survey  
thereafter.



© 2020  
Lloyd's Register  
Foundation