

1

Sent to Chief Surveyors 16. 11. 22. "

Received from Chief Surveyors 10 NOV. 1922

VESSEL'S NAME

s/s Peken.

Report Low.

No. 86065-2

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Boiler

When due 2. 22.

Screw shaft 5. 22.


The examination of the screw shaft became due in 5. 22. & the boiler survey became due in 2. 22. no part has been held.

The Owners state that they have decided to withdraw the vessel's class from the Register Book.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the Owners' request.

Withdraw class.
Insert ...

KD
16/11/22



© 2020

Lloyd's Register
Foundation

007572-007589-0036