

1

Sent to Chief Surveyors 31. 10. 16.

1 NOV 1916

Received from Chief Surveyors _____

VESSEL'S NAME

S.S. Loon.

Report

Hul

No.

29604^a**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


Screw shaft

When due

7. 16.

The Examination of the screw shaft became due in 7. 16.
The Owners now state that it is not their intention to return the vessel in class.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof indicating that the class has been withdrawn at the request of the Owners.

Withdraw class.Insert . . .DRKJ.W.D.31/10/16.C.F.

© 2020

Lloyd's Register
Foundation