

M.L. 1
"M.L. 2"
M.L. 3

ST. CHANGNAM

The BANGKOK Surveyor should be informed, in answer to his letter dated 2.1.47, that the requirements of a PERIODICAL SPECIAL SURVEY (C) (formerly S.S. No. 3) should be carried out. As, however, it appears that a considerable number of shell plates may require to be renewed the Surveyor may deem it advisable, in view of the fact that the vessel is now 20 years old, to comply with the requirements of a Special Survey (D) (2nd S.S. No. 3), which includes drilling of the shell plating.

The Surveyor should satisfy himself that the material used for the repair of important parts of the structure has been manufactured by the Open-Hearth process and is in accordance with the Society's requirements.

Replied Regd. 24/1/47

on "Changnam", "M.L. 1" & "M.L. 3"



© 2020

22.1.47
Lloyd's Register
Foundation

007572-007589-0093