

11

8 DEC 1939

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME

M.L. 2

Rpt.

Bgh.

No.

1299

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

rvey

The *Bangkok* Surveyor's report this vessel placed in dry dock, bottom cleaned and coated, repairs or renewals to a keel plate and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 10.39 as recommended.

100 A1
Barge for being towed
10.39 Bgh.



© 2020
Lloyd's Register
Foundation

007572-007589-0097