

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 29/11/09... When handed in at Local Office... Port of Glasgow  
 No. in Reg. Book... Survey held at Glasgow... Date, First Survey 8th Nov 2... Last Survey 23rd Nov 1909  
 27 Lagg, the Wood, Iron or Steel S.S. Lord Stalbridge... Master

TONNAGE:— Built at Dublin By whom Dublin D. Y. Co. When 1909 9  
 GROSS 164 Owners Shropshire Union Rly & Canal Co. Port belonging to Chester  
 UNDER DEK. 152 Owners' Address  
 NET 61 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Princes. Destined Voyage  
 WB=CellDBorDBa feet; uE&B feet; f feet; f  
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.  
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
 A. 1.  
 For River & Towing purposes  
 Class Contemplated  
 Society's Freeboard (if assigned) as painted on Ship and now verified ft ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion  
 The Engine & Boiler Casings have now been efficiently closed in and rivetted up.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

  

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" Rule length size
Floors		Stringers, Clamps & Shelves ditto	" Rule length size
Keelsons		Salting (State if examined.) ditto	Mawser & Warps
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—  
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,07," or "to remain as classed and to have record of survey, 1,07, and the notations of ss No. 1-07 and ptND07, &c."  
 The above is for the information of the Committee

Survey Fee (per Section 25) £ : : Fees applied for, 19  
 Special Damage or Repair Fee (if any) £ : : Received by me, 19  
 Travelling Expenses (if chargeable) £ : :  
 Second Surveyor's Fee (if any) £ : :  
 J. H. Mackellar  
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute GLASGOW 30 NOV. 1909  
 Character Assigned Transmit to London.

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so, to be sent to

10m38.—Transfer Int. The Surveyors are requested not to write on or below the space for Committee's Minute.

