

2m.0.29.

Subject to the mudder mainpiece repaired by electric welding 10.23 the stern
frame repaired by the same process 5.25 + 3 by being specially examined at next
dry docking & the stream-line plates of the mudder being permanent repaired
at the Owners' convenience.

3

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

M. S. "LIVERPOOL MARU"

Rpt.

Hak

No.

117

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

1st S.S. No. 3 AND DAMAGE.

Damage through

stranding, salvage operations & heavy weather.

now repaired as follows:-

(see Ham Rpt 19756)

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	84	60		106			
Removed and faired or repaired.....	34	230	1	115			
Faired or repaired in place.....	19	26	4	26			

Other items:-

Vessel placed in drydock, a new stern frame & rudder fitted in
accordance with approved plan, stern partly renewed, repairs effected to centre girder,
intercostals, tank margin, tank side brackets, tank top, bunkers, bulwarks &c and
minor repairs carried out.

The 1st S.S. No. 3

has also been held and following repairs done

due to wear and tear:-

Bottom coated, repairs effected to a shell plate, decks,
bunkers, floors & minor repairs carried out & some additional stiffening fitted to deck girders
at hatch corners.
Shell plating drilled as necessary & found in order.

The Surveyors recommend a length of chain cable be supplied to replace a length
worn below the rule minimum.

It is submitted the vessel is worthy to remain as classed, with record

of Survey

11.31

and notation of

S.S. No 3-11.31 subject as recommended
but without other condition.

as recommended.

100A1

Aung dt with Jhd

11.31 Hak

S.S. Hak No 3-11.31

Subject &c

Without &c



© 2020

5.12.31

Lloyd's Register
Foundation

007620 - 007625 - 0128