

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S/S "WILLIAM DOAK"

Sou. 11273  
Rpt. Off. No. 43326

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ature of Survey

Dimensions 138.33 x 23.62 x 13.5

Scantling Nos. 37.12 and 5134.8

Proportions Length. 10.24 depths.

The vessel was built in 1918 under the Survey of the British Corporation to plans mutually approved by this Society and the British Corporation for the Mersey class trawlers.

Reports have now been received from the Cardiff and Southampton Surveyors at whose ports the vessel has been under survey with a view to classification, giving particulars of scantlings, Etc., which are generally in accordance with those approved.

The vessel has been examined on a slipway and the requirements of Sec. 48 of the Rules complied with and an S.S. No. 3 carried out.

A bower anchor and 30 fathoms of chain cable supplied and minor repairs effected.

The workmanship appears to be good.

100 Al Stm trawler.

1 Dk. Stl. WS.

Bk. 7 $\frac{1}{2}$  3 BH. Cem. Lloyds A & C.P. Q 78' F 19'

Date of Build 1918

6.22 Sou.

S.S. Cff. No. 3 4.22

W.L.



© 2020

28-6-22

Lloyd's Register  
Foundation