



# Lloyd's Register of Shipping,

LLOYD'S REGISTER

LONDON.

10 MAY 1922

REC'D

AND

Merchants' Exchange, Bute Street,

Cardiff,

9<sup>th</sup> May 1922.

Dear Sir,

In reply to your letter of 5<sup>th</sup> inst regarding First Entry Report no. 43326 on the Steel Screw Ketch "WILLIAM DOAK" I beg to state that there is a watertight bulkhead fitted on frame 79, also the size of the reversed frames on the floor is 22" x 22" x 30".

Also the special survey held now may be considered as equivalent to part of a Special Survey No 3 and it was not considered necessary to drill the shell plating.

Also that, with the exception of the items stated in the report as remaining to be done to complete the survey, the requirements of Section 48 of the Rules have been complied with.


In my opinion the stiffening of the bulkhead on frame 71 is satisfactory.

I am, Dear Sir,

Yours faithfully

J. Buchanan.

The Secretary.  
London.



© 2020

Lloyd's Register  
Foundation



Referred to the Chief ~~Chap~~ Surgeon.

*CR*

WED. MAY. 19. 1912

Arrive Southampton Report  
BH  
10/5/12



© 2020

Lloyd's Register  
Foundation