

# Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 6th. May 1930.

No. 2499.

This is to Certify that at the request

Messrs. Mitsubishi Zosen Kaisha, Ltd., Kobe Works,

Open Hearth Steel Forgings ~~XXXXXX~~ named below ~~was~~ were examined and  
at their works on 7th. Nov. 1929 and subsequent dates

found to be as far as could be ascertained, sound and free from defect.

Two (2) piston rods, 70 m/m diam. x 685 m/m long, for

Auxiliary Air Compressors in finished condition.

~~XXXXXX~~

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x 1/2" x 180°
1 E 9	30.42	32	Good
1 E 10	30.90	32	Good

These Piston rods are intended for Nagasaki Ship No. 474.

and ~~has~~ have been stamped as follows:-

Yen ) See Debit  
) Note.

288.130.2888


: 71 E 9 :	: 71 E 10 :
: LLOYD'S :	: LLOYD'S :
: No. 2499A :	: No. 2499B :
: H.D.B. LR :	: H.D.B. LR :
: 3-5-30 :	: 3-5-30 :

H. D. Buchanan.

Surveyor to Lloyd's Register.

certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy  
of the certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the  
any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."

Y 12 1930



Lloyd's Register  
Foundation

007679-007687-0216



72

# Lloyd's Register of Shipping

(MEIKAI BUILDING)

35, AKASHI-MACHI,

KOBE, Jpn. May 1930.

No. 2499. Cert.

This is to Certify that at the request

of Messrs. Mitsubishi Bussan Kaisha, Ltd., Kobe Works,

the Hirth Steel Forgings Co. Ltd. named below were examined and tested at their works on 7th Nov. 1929 and subsequent dates

and found to be as far as could be ascertained, sound and free from defect.

Two (2) piston rods, 70 m diam. x 685 m long, for

Auxiliary Air Compressor in finished condition.

Test Mark	Mark	Tensile Tons in	Elongation % in 2"	Bend 1" x 1/2" x 180°
71	2	30.45	35	Good
71	10	30.30	35	Good

These piston rods are intended for use in the ship No. 474.

and have been stamped as follows:-

71 2	71 10
LLOYD'S	LLOYD'S
No. 2499	No. 2499
H.D.B. LR	H.D.B. LR
3-5-30	3-5-30

See Debit Note

Surgeon to Lloyd's Register.

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be  
that the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy  
or report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the  
a for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society.



Lloyd's Register  
Foundation

000F00-PF00F00-0000

24 June 1930 12.18.24.26.30 July 21.5-9.17.22.23.24.25.28.30 Aug 1.4.

High Press

Seamless, lap