

the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water

nes

No. 5291.

Made by

Sulzer Freres S.A.

Stock.

Winterthur Report No. 32

It is submitted that further action in the case is

unnecessary until ~~as this boiler is not intended for~~ *these Engines are* fitted on a

classed vessel.

JWD

Date

11/4/23.

Entered in "Unclassed" Boiler Book.

© 2020

Lloyd's Register Foundation

007679-007687-0269

If a wood vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturation