

13 JAN 1941

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"TANAIS"

Rpt. Pir

No. 5054

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The class is subject to indented shell plating, on port side forward, being repaired at the Owners' convenience.

The PIRAEUS Surveyors report the vessel placed in dry dock, bottom coated.

A partial General Examination has been made.

The indented plating, as above, examined and found efficient.

It is submitted the vessel appears worthy to remain as classed with record of survey 11.40, subject as above.

100A1 )  
11.40 Pir ) Subject, etc.

*RGD*  
10.1.41

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register  
Foundation

007707-007713-0131