

cases where the Surveyor has not made a special damage report he is required to state whether he  
his services for this purpose, and why they were declined

Attached

S.S. Sea. No. 1-36  
M. S. ...

2 E

Chief Engineer Surveyor  
NAME *Hester.*

Received from Chief Engineer Surveyor

Rpt. *Aly P.H.* No. *2045-3180*

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02)

~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due *4.40* now ~~partly~~ held ~~now~~  
pleted, and ~~the following~~ repairs carried out (due to *wear tear & -*  
*foundering damage*)

It is submitted the vessel is eligible to remain as classed, with  
tion of *B/S 540.* as recommended.

*J.P.*  
19/9/40

© 2020

Lloyd's Register  
Foundation

007714-007721-0317

Necessary to keep the Ballast and General service pumps  
recommended the two pumps be thoroughly overhauled.