

S.S. Commercial Traveller

Sea 1149.

Damage through grounding & subsequently striking a Spit.

Leeward shaft of propeller removed crank shaft lifted & shafts realigned & several repairs effected. Boiler surveys held

It is submitted that this vessel is eligible for
THE RECORD. + L.M.C. 4.23

N.S. 4.23.

L.S. 4/6/23

It is concluded that the M. & L.P. cylinders & pistons, all slide valves, pumps & other connections & the condenser have been examined but the surveyor should confirm this, & in future cases when reporting surveys for the record of G.N.C. or for periodical surveys he should report his examination in detail & variation in terms of the Rules as per heading of report.

S.O. 14/6/23



© 2020 see letter 5/7/23

Lloyd's Register
Foundation

007714-007721-0344