

to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "MONKAY" REPORT Liv. No. 123712

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Part of Survey Docking, Damage. ~~How done~~

[ Subject to indented shell plate H.12  
etc. (s.s.f) being dealt with at the first convenient  
opportunity, to sternframe rudder post at top E.W. 1.46  
being specially examined at the next dry docking, to cargo  
battens being fitted at the first opportunity and to  
(a bower anchor and 60 fathoms of chain cable being supplied). ]

2.46 Liv.

(85)



© 2020

4.3.46.

Lloyd's Register  
Foundation

note change of owners etc.

007722-007730-0044