

007739-007745-0008

to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME EMPIRE PENRYN

REPORT Sws.

No. 24180

For the CHIEF SHIP SURVEYOR and ~~CHIEF-ENGINEER-SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24 /5/92.)

of Survey.....

When due.....

The validity of the "Examined" notation expired 3.48.

The vessel was last submitted to Special Survey 6.37.

ACTION is DEFERRED for repairs and notation of "Laid up pending repairs" is recorded in the Register Book.

The Ministry of Transport, in reply to an enquiry, stated by 'phone 26.8.48 that classification of this vessel by the Society would no longer be required (see endorsement 26.8.48).

It is submitted the vessel's character be expunged from the Register Book and a red line (—) with date inserted in lieu, signifying non-compliance with the Society's Rules as regards surveys.

Expunge class

and insert (—)



© 2020

Lloyd's Register
Foundation

157.
8.9.48
L.A.N.