

WANSEA 3860.

RECEIVED

8 APR 1948

Sir,

Lloyd's Register of Shipping,

Letricheux Buildings, Adelaide Street,

Swansea, 7th April, 1948.

2 plans
 S.S. "SINAI".
 ex "H.M.S. "LUCIA" ex "SPREEWALD".

Phystruck 3174

Mr. Landy, Owners Representative, and Major Hambling, Consultant, discussed the question of Classification and issue of Load Line Certificate for the above vessel now lying at this port.

The vessel was built in 1907 by Messrs. Furness Withy at West Lepool for German Owners to Germanischer Lloyd Class and was purchased in 1916 by the R.N. and used by the Admiralty under the name S.S. "LUCIA" until purchased recently by the Compania Maritima Geofunior, S.A., Panama.

We enclose herewith midship section and profile plans for your information.

Permanent cement ballast 2' 0" high stated to be fitted on the tops in all holds and at the forward end of the Boiler Room and Owners Representative wishes to retain this meanwhile, Pig ballast also fitted at the after end of the Engine Room.

Mr. Landy and Major Hambling wish to have a decision as soon as possible in order to give instructions to the Repairers for carrying out the necessary survey. Mr. Landy requested that he be advised by you at his address:- 78 New Oxford Street, W.C.1. and that you could call personally with Mr. Hambling if this was deemed necessary to discuss requirements or give any further information that may be required.

Museum 7351

Spreevald 3051

Lloyd's Register Foundation

007806-207816-0167

Referred to the Chief Ship Surveyor,
and the Chief Engineer Surveyor,

Referred to the Chief Ship Surveyor
(Freeboard) *Copy to the Board*

The Secretary,
LONDON.

also for Mr. Ferris to note.

Also for Mr. *Chinn* to note.

REQUESTING EARLY REPLY

Dealt with by
Hd. 9/14/45

The question of tonnage measurement in this case was to and we shall be glad to have your guidance on this point of view of the vessel being under the Panamanian Flag.

We are, Dear Sir,
Yours faithfully,
The Surveyors,
Per:-

GRM

*The Surveyors' Reports
abroad have measures for
Panama. Authorities
instructions from 1912.*

© 2020

Lloyd's Register
Foundation