

Sm. 3, 21.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel T.S.S. "bonte Verde."* Report *Glo.* No. *42623.***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)



Nature of Survey

When due

*Damage sustained through striking quay wall.  
Vessel placed in drydock, bottom and rudder cleaned and  
re-coated, and damage repaired as necessary.*

*✱ 100. A.1 (Steel) "with freeboard"  
2 Dks (Stl) & Shelter Dk (Stl) & Shade Dk (Stl- teak s)  
3<sup>rd</sup> Dk (Stl). in holds.*

*Cell DB 478' 1468 t, DT f 15' 676 t, FPT 85 t, APT 96 t.  
FK, 9 BH to Shelter Dk, Cem, Lloyd's Arch. B327, F50' on Shade Dk.*

*7/4/23.*

007817-007824-0056