

# Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 27th January 1930.

Cert. No. 2373.

This is to Certify that at the request

of Messrs. Mitsubishi Zosen Kaisha, Kobe Works,  
the Open Hearth Steel Forgings ~~connecting~~ named below ~~was~~ examined and  
tested at their works on 26th October 1929 and subsequently,  
and found to be as far as could be ascertained, sound and free from defect.  
Six off, Auxiliary Diesel Engine Connecting Rods  
in finished condition.

Drop tests: -- --

Test Mark	Tenacity Tons/sq in	Elongation % in	Bend
95 B 6 2 off	32.45	33.0	Good
95 B 7 2 off	32.89	32.0	"
95 B 8 2 off	32.57	33.0	"


These connecting rods are intended for Vessel No. 473.  
Nagasaki. and ~~has~~ been stamped as follows:-

Fee Yen {  
Expenses ,, { See Debit Note.

LLOYD'S  
No. 2373.  
W.K. LR.  
25-1-30.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."





104

# Lloyd's Register of Shipping

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 27th January 1930.

This is to Certify that at the request

of Messrs. Mitsubishi Bussan Kaisha, Kobe Works, the Open Hearth Steel Forgings examined before were tested at their works on 26th October 1929 and subsequently found to be as far as could be ascertained, sound and free from defect. Six off-shoots of steel pipe connecting rods in finished condition.

Drop tests:

Test Mark	Tenacity Tons/in	Elongation % in	Bend
95 2 6 2 off	32.45	33.0	Good
95 2 7 2 off	32.89	32.0	"
95 2 8 2 off	32.57	32.0	"

These connecting rods are intended for Vessel No. 473. and have been stamped as follows:-

See Debit Note. 25-1-30. H.D.B. 10-4-30. H.K. I.R. No. 2373. LLOYD'S No. 2373.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
“While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of the Surveyors, other Officers or Agents of the Society.”

