



Lloyd's Register of Shipping,

97 & 98, Scottish Provident Buildings,
Donegall Square West,

Belfast, 29th. May, 1920.

LLOYD'S REGISTER,
LONDON.

RECD 31 MAY 1920

ANSR

Reference

The Secretary,
LONDON.

Sir,

In reply to your letter of the 27th instant respecting the First Entry Report No.8336 on the S.S. "PORT CURTIS", we beg to state that there are nine $\frac{7}{8}$ " rivets fitted between the frames in the rows of edge riveting as approved in your letter to Messrs. Workman, Clark & Co. dated 28th June, 1918.

A hand pump has been fitted to the compartment above the fore peak tank.

No insulation is fitted in the Shelter tween deck spaces.

We are, Sir,

Your obedient Servants,

The Surveyors,

per *J. W. H. H. H.*



© 2020

Lloyd's Register
Foundation

007825-007833-0220

Referred to the Chief Ship Surveyor.

Also for Mr. Hill to note
31 MAY 1957
CSA

Handwritten signature/initials

Box

the enclosure.

your obedient servant

As also, Sir,

No information is given in the letter as to what work was done
to the body tank.

A hand pump was seen fitted to the compartment above the
to the tank. A drawing of the pump was submitted with the
letter in the case of the letter as enclosed in your letter
and to state that the pump is fitted to the tank between the
the letter with reference to the S.S. "LORD CURLISS". The
the letter to Lord Jellicoe of the work in progress.

Yours faithfully,
The Surveyor

CSOJ, VAN. 11788



© 2020
Lloyd's Register
Foundation



LLOYD'S REGISTER, LONDON