

Rpt. 8.

DISCLOSED
SECTION No. 115313A

(Received at London Office)

No. 115313A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... When handed in at Local Office... 19... Port of LONDON

No. in Survey held at... Date, First Survey... Last Survey... 19... 3 60

Reg. Book. Supp 16488 on the Wood, Iron or Steel Ing "BIZON"

TONNAGE:— Built at... By whom R. Dunstan Ltd. When 1942 12
GROSS 129 Owners Gdynia-America Shipping Lines Ltd. Owners' Address...
UNDER DK. 123 Managers... Port belonging to Gdynia
NET

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...
Cell D Bor D Ba... feet; uE & B... feet; f... feet
total capacity... tons. FPT... tons; APT... tons; MT... feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 115668. Port Lon

Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :—
Renewed ...								
Removed and Faird or Repaired								
Faird or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Caulking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Coamings	Rudder	Scuppers	Boats
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Keelsons		" " at other places	" Rule length size
Stringers		Stringers, Clamps & Shelves	Chain Locker
Inner Bottom Plating		Salting	Hawsers & Warps
Have the Tanks been examined internally?		State if examined.	Standing and Running Rigging
Have the Tanks been tested?			Sails

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

See minute 2.1.408
(11)

Surveyor to Lloyd's Register of Shipping



Lloyd's Register Foundation

007846-007856-0077

MADE AND PRINTED IN ENGLAND.

Is Certificate required? If so, to be sent to