

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"MARGARET ROSE"

Rpt. Msl.

No. 10051

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey

SPECIAL SURVEY OF ~~ENGINES AND/OR~~ BOILERS PARTLY HELD ~~FOR S-S-NO~~~~LMC~~~~LMC(M)~~~~MS~~

BS

due 10.39 , partly held

~~now further advanced~~ and the following repairs effected (due to theft):-

Various boiler mountings renewed.

One propeller blade found broken.

The Surveyors recommend the propeller be renewed on

arrival in the U.K.

It is proposed to complete the survey on arrival in the U.K.

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record

BS 4.40 when the survey has been completed. subject as recommended.

The following remains to be done to complete the Survey

Adjust safety valves.



© 2020 7.5.40

Lloyd's Register
Foundation

007865-007873-0227