

007881 - 007887 - 0022

4 E

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

EL'S NAME "MILIANA" ex. "EMPIRE BUTE" REPORT Alg. No. 1682

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey ~~REPAIRS - TO - ENGINES - AND - BOILERS - DUE - TO - DAMAGE - THROUGH -~~

Screw shaft examined and found in good condition. Boiler examined throughout and machinery generally examined, minor repairs effected.

These surveys were held at the Owners request but are not yet due.

The Surveyor recommends the record of S 4.47. It is considered that the record of BS 4.47 could also be assigned at this time.

for the Record BS 4.47,
S 4.47.

IT IS SUBMITTED that this vessel is eligible

8. 5. 47.

