

D. 392

17 MAR 1947

to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME

American Fisher

Report

Notes.

No. 6246

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Date of Survey..... Damage due to striking bank When due.....

Class is subject to propeller being specially examined
at next docking

The surveyor now recommends permanent repairs to
be applied to propeller & screw shaft & machinery as stated.

It is stated the vessel is laid up pending repair

Notes

Thru

12.3.47

© 2021



007881-007887

Lloyd's Register
Foundation