

COPY.

(SEE SFO. REPORT NO. 7722)

Lloyd's Register of Shipping.



Port . SAN FRANCISCO

August 20th, 1937.

This is to Certify that I have

surveyed the Boiler⁸ and Machinery of the S. S. "AMERICAN FISHER",
779 tons gross register, of San Francisco, while lying afloat
and on drydock at this Port for damage due to explosion and fire
on 24th, 1937 also B. S. and part M. 9.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
recommended that the record of B. S. 8-37 and M. S. 8-37
on survey has been completed

made in the Register Book in the case of this vessel.
(Damage repairs now completed.) (Repairs to Preheating tube
stem in W. T. Boiler to be effected at Owners' convenience.

(Signed) F. G. ARCHBOLD

Engineer Surveyor to Lloyd's Register.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is
provided that neither the Committee nor the Society are under any circumstances whatever to be held responsible for
any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other
of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents

007881 - 007887 - 0193

Lloyd's Register
Foundation