

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME *SS S. AMERICAN FISHER* Report *S. To* No. *7612*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey *Alterations for carriage of* When due *petroleum in main cargo tanks only.*

Subject to stern frame repaired by (E.N. 7.35) being specially examined at next dry docking & to 440 volt electrical installation not being used while carrying petroleum

Amend Class to

*100A1
Light Reduction Ship.
Carrying petroleum in bulk in main cargo tanks only
Fitted for oil fuel F.P. above 150° F.*

N.A.B.
G.S. 842



© 2021

Lloyd's Register
Foundation

007881-007887-0203