

The class is subject to the generator main cables being replaced by cables applying with the Rules at the first opportunity. **5 E**

29 JUN 1949

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME "WINSTON SPENCER CHURCHILL" REPORT Ant. No. 25363.

emarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

- (“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey

DAMAGE - 3 WEAR AND TEAR.

Docking.

Propeller renewed.

It is submitted the vessel is eligible to remain as classed, with-

~~Record of Survey~~

as recommended, subject as above.

29.6.49.

*Thur*

007888-007894-0040