

short circuited, or touched
Are the lubricating arrangements of the generators
Compound wound generators - But port side 1st start side engine room.

(Italy.)

LLOYD'S REGISTER AND REGISTRO ITALIANO.
FEES FOR DUAL CLASSIFICATION SURVEYS.

Port **TRIESTE** Date **June 4th,** 19 **27**
Name of Ship **"RIALTO", Stabilimento Tecnico Triestino No. 751**
Number of Report **7546 (Elec.)**

Total <u>Lloyd's Register</u> fee	Lit	<u>4.004.-</u>
Total <u>Registro Italiano</u> fee	Lit	<u>2.779.-</u>
Total fees	Lit	<u>6.783.-</u>
COMBINED FEE, i.e., 5/6 (LR + RI)	Lit	<u>5.652.50</u>
52 per cent of 5/6 (LR + RI) to be credited to Registro Italiano	Lit	<u>2.939.30</u>
48 per cent of 5/6 (LR + RI) to be credited to Lloyd's Register	Lit	<u>2.713.20</u>

Travelling Expenses charged (to be credited to Lloyd's Register)... Lit

007909-007918-0116

main sv

pole circuit breakers with maximum ant reverse current trips and with equ