


S. S. "Parent"

Convention freeboards have not been assigned to this vessel and Mr. Rowden states that freeboards are not now marked on the vessel's sides.

It is therefore submitted the records of freeboard and draught be expunged from the Register Book.

WBS

400 1/2



© 2021

Lloyd's Register  
Foundation

007938-007946-0084

LL  
VS