

28.7.18.

1

Indian Prince

Sent to Chief Surveyors 15.10.17

Received from Chief Surveyors

VESSEL'S NAME

Steel ss Glenlyon

Report

Lb

No. 37146

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

100 A-1. (Steel)


2 A-6 (Steel)

Cell DB 344 1066 E. D.T. a 33 890 E. A.P.T. 246

F.K. Ties on Bulkhead in aft hold dispersed with

5 B H E upper deck 1 B H 6 2" 50 only

few hysd used. P 35 B 121 F 45


 15.10.17


© 2020

Lloyd's Register
Foundation

007947-007957-0073

Spacing
BEAMS, Poop Deck, Angle, Bulb Angle, Plate,
Top Bulb or Channel

7 1/2	3	44	7 1/2	3	44
-------	---	----	-------	---	----

Deck, material and thickness
Bridge Deck Stringer Plate, br'dth & thickness
Angle on ditto