

007947-007957-0182

Surveyors _____

Received from Chief Surveyors _____

NAME *Stul SS. "TERNEUZEN"*

Report

JK

No. *17977*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/503.)

Survey _____

When due _____

Intermediate bulkhead in forward hold dispensed with, (Owner's letter attached)

100-A-1. (Stul)

12K (Stul)

Cell DB 248' 638t, FPT 90t, APT 12t,

FK, "Intermediate bulkhead in forward hold dispensed with. A Bl. only."

Curr, Lloyd's A. CP, PZS' 158' F35

Concluded that a Semi-bow beam is fitted on the Collision bulkhead as approved but the
regus Shenas State of this is 50

23-3-23

KNESS