

*Built 1928/4.*

NAME HWA LOONG 4 (BULIMBA.)

Report

No.

KNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in <sup>THS.</sup>  
100 of an inch.

	AMIDSHIP.				FORWARD.				AFT.				REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.	Original Thickness.	Thickness by drilling.		Diminution if any.	Original Thickness.	Thickness by drilling.		Diminution if any.	
		Port.	Std.			Port.	Std.			Port.	Std.		
STRAKE	40				26	PEL SIDES.			32				
H	40								32				
G	36				32				32				
F	36				32				32				
E	36				32				32				
D	36				32				32				
C	36				32				32				
B	36	MAINTAINED TO COLL. BHD.			32				32				
A	36				32				32				
AL.	40				42				42				
									</				

*This copy to be returned in office*

2020

12-1-48

Lloyd's Register Foundation

Drillings at ends to be made in the vicinity of the peak bulkheads.

007958-007966-0041