

Chief Surveyors

Received from Chief Surveyors

EL'S NAME

CORCYRA

Report

LIV.

No. 114261

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.


(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey GEN. Ex. FOR POST^{NT} OF ~~279~~^A S.S. N^o 1 ~~When~~ due 6-39 TILL 11-40. "EXAMINED 5-40" ASSIGNED.

Stem bar (set over) requires to be dealt with at the
Owner's convenience

Repairs are required to stokehold ventilators^{etc} at an early date

The shell plating requires to be dulled at this S.S.



© 2020

Lloyd's Register
Foundation

007938-007936-0115