

1

7458 R.B.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Sheela Sapulpa

Report

S 2

No. 3344

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

When due

✕ 100 A-1 "fanning petroleum in hulls"

2 DRs (Steel) & Webframes. Longitudinal framing


Cee D.B. = E+B 6i 1436. D.T. f 43' 5406 A.P.T. 286

F.R. 16BH (9 1/2 upper & 7 1/2 DRs) pl-asp. A x E.P.

P. 106. B 40 Fui Mchly abl.

Date of Build 6.20.

See enquiry re prop side plating in report for vessel
vessel 'Salina'



© 2020

6.9.20

Lloyd's Register
Foundation

007958-007966-0205