

5/6 "John Anderson."

Hull. Rpt 30310

It is submitted, the Hull Surveyors be informed that it is concluded a spare set of feed & bilge pump valves have been placed on board, but as no mention of this is made in their report they should be requested to state whether this is so.

AWD

3/1/18.

Lloyd's Register
Foundation

067488-067497-0036

BK 72 4BH. Gen. Lloyd's Reg. Q 71