

F.E.

Chief Ship Surveyor 1.1.18 Received from Chief Ship Surveyor

NAME Sheelss "John Anderson" Rpt. Incl No. 30310

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

verse No. 35.71 Depth "d" 11.75
ng: Table No. 3 page 9 Description Single Angle as approved
tudinal No. 4463.

Proportions Length = 9.55
Depth

~~Deck~~ Sheerstrake -62 of an inch instead of .34 as reqd.

This vessel appears to have been built in accordance with the
and the approved plans, and it is submitted she is eligible to
assessed 100A.1 (Steel) "Steam Trawler", as recommended.

I.D.K.
BK 7 1/2" ABH. Cen. Lloyd's R. Q 71

M
1.1.18



© 2020

Lloyd's Register Foundation

007988-007997-0037