

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

5th December 1910.

Sir,

With reference to your first entry report No. 4684 on the new steel motor lighter "CORNELIS", I have to request that you will be so good as to state whether the tank top plating is .30" as given on the report or .32 as required if intermediate reversed frames are not fitted.

In view of the classification certificate being required at the earliest convenience, I have wired you this afternoon as follows, viz:-

"CORNELIS state whether tanktop plating point thirty  
'  
"or thirtytwo enniano (-as required by the Rules)  
"if intermediate hartemos (-reversed frames) not fitted".

I am, Sir,

Your obedient Servant,

J. B. Slebe, Esq.,  
AMSTERDAM.



© 2020  
Secretary.

Lloyd's Register  
Foundation

007988-007997-0191