

cpo "Cornelis."

Ams. Rpt. No 4684.

It is submitted that the Amsterdam Surveyors should be requested to state, whether the number & sizes of the electric lighting cables as given on the report are correct, as they do not appear to agree with the areas given. It should also be pointed out that the area of the cables should equal one square inch per 1000 amperes. This report should be returned.

Lr: 15/12/10

Lloyd's Register
Foundation

007488-007497-0199