

Iloilo., 23rd Oct., 1941.

Messrs. Smith, Bell & Co., Ltd.

Lloyd's Agents,

Iloilo.

Dear Sirs,

In connection with the attached reports on the M. V. Kanlaon II there are several items which will have to be arranged with the owners in Manila.

On such things as tail shafts and anchor cable a certain amount of latitude must be given as they are almost unprocurable at the present time.

I have no copy of Lloyd's Rules so don't know just how much latitude to allow and have left that to Mr. Nelson, who can bring pressure to bear on the owners in Manila.

Getting anything done here is difficult as it is only a branch office.

Yours truly,

*H. Henry*  
H. Henry

*Isled  
J. J. J.*



© 2020

Lloyd's Register  
Foundation