

1944

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office... Port of London No. 426
 No. in Reg. Book... Survey held at... Date, First Survey... Last Survey...
 on the Wood, Iron or Steel SS BEDA

TONNAGE - Built at... By whom... When... MONTH...
 GROSS 300 Owners... Address...
 UNDER DK. 220 Managers...
 NET 165

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...
 Ceil D B or D Ba... feet; uE & B... feet; f... feet
 total capacity... tons; F.P.T... tons; A.P.T... tons; M.T... feet tons.

Only alterations in the existing records of tanks should be inserted.
 N.B. All alterations in the existing records should be underlined.

Last Report, No. 7094 Port SKM

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
 CHARACTER...
 +100A1
 12.46
 SS Skm 24123-033
 8 Skm-4.46(24)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
 Society's Freeboard (if assigned) as painted on Ship and now verified... ft... ins

Was a damage report made by anyone else? if so, by whom?
 REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if as Felt)
Caulking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month... Year...
Coamings	Rudder	Scuppers	Boats
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
" in way of sidelights	Have pumps been examined and found efficient?	Planking	(State if with or without)
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment, letter
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Age... No. of
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stimson	Length... beam... depth...
Transverses	Alr and Soundng Pipes	Transoms, Pointers & Crutches	Check Loose
Floors	Soundng Pipes under Soundng Pipes	Timbers of Frame at openings	Drawers & Wagon
Keelsons		" at other places	Standing and Running Rigging
Stringers		Stringers, Clamps & Shelves	Sails
Inner Bottom Plating		Salting	
Have the Tanks been examined internally?		State if examined.	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-

Sample :- "This survey... as classed in the Register Book without fresh... of Survey."

Survey Fee under Section 20	Fee applied for
Special Damage or Repair Fee (if any)	10
Travelling Expenses (if chargeable)	Received by me
Second Surveyor's Fee (if any)	10

Committee's Minute... Character Assigned...
 FRI 25 MAR 1944
 Withdraw class & insert (...)
 Surveyor to Lloyd's Register of Shipping.
 General Committee
 Thursday, 7th April
 Lloyd's Register Foundation