

24 OCT 1935

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

No. 1 SURVEY PARTLY HELD.NAME (STEEL 4 Mst. BK) MOSHULU Rpt. GOT. No. 12612

Marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

e 3RD S.S. No. 1 due 7-39 has now been partly held as

as:-

The greater part of the Survey has been held.
A hand pump requires to be fitted for
the suction pipe in the fore peak.

~~The following repairs done (due to minor repairs effected~~):-

It is proposed to complete the survey *when ballast discharged at Buenos Aires where bound. Surveyors advised.*

It is submitted this proposal might be approved and ~~the vessel be~~

~~ved to remain as classed, record of Survey and notation of~~ S.S

~~7 being deferred until completion of same~~

action deferred.

the following remains to be done to complete the 3RD S.S. No. 1

*Hold in way of sand ballast to be examined
Hand pump to fit.*

© 2020

Lloyd's Register Foundation

008068-008078-0233

008068-008078-0234

007003-008078-0630