

4 E

20 AUG 1948

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME "FOSSUR" REPORT L.A. No. 12227

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

by REPAIRS TO ~~ENGINES-AND-BOILERS DUE-TO-DAMAGE-THROUGH-~~

Boiler Survey became due 1.48.

A report has now been received from the Lloyd's Agent Surveyor at Thorshavn stating that a previous welding repair in the starboard furnace of the boiler had been cut out and re-welded. The boiler was afterwards tested.

IT IS SUBMITTED action be deferred for the Boiler Survey to be held.

19. 8. 48.

008089-008095-0145