

Surveyor

Received from Chief Ship Surveyor

22 SEP 1924

Stl. Sc. Sr. "BRAVORE"

Rpt. Bry.

No. 19383

Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The s.s.No.2 became due 2,24.

The class is subject to some indented shell plating
alt with at the Owners' convenience.

The Barry Surveyors now report the vessel placed in
, the bottom cleaned and coated and minor repairs effected.

The indented plating examined and found efficient.

No arrangements could be made regarding the special
at this time.

It is submitted action be deferred.



© 2021

19.9.24.

Lloyd's Register
Foundation

008087-008095-0214