

ent to Chief Surveyors.....
GB

Received from Chief Surveyors.....

SHIP'S NAME

"ARAKOON"

REPORT

No.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey.....

~~XXXXXX~~

This ship (29 years old) is classed
BS* "With Freeboard" and the last record of drydocking
is 7,53.

There is a Notation "Laid Up - Surveys Overdue"
in the Register Book.


A SPECIAL SURVEY (D) became due 7,55.

In a letter dated 7.10.55 the Sydney Surveyors
advise Owners' request for the class of this ship to be
withdrawn.

IT IS ACCORDINGLY SUBMITTED for consideration
whether the class of this ship be expunged on
account of non-compliance with the Society's
Rules as regards Surveys.

EXPUNGE CLASS and
INSERT IN R.B.

Class Expunged - Non-compliance with Regulations 10,55.


13.10.55.



© 2020

Lloyd's Register
Foundation

008096-008100-0114