

bottom Anodes / double

ent to Chief Surveyors

Received from Chief Surveyors

ESSEL'S NAME She. Sc. M/v. LAUREL Report Gls. No. 50695

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(in cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/53.*)

so that the Clasing Committee may have all the salient points presented in the enclosure.

Signature of Surveyor 1st Entry When due Revised Rules.

✕ 100A1 (Steel) carrying petroleum in bulk.
 2 D^Ks (Stl) & Webframes. Longitudinal framing.
 Cell DB w^h 72' 238t, DTf 41' 446t, FPT 221t, APT 97t.
 FK, 16 BH (15 BH to upper D^K, 1 BH to 2nd D^K) Lloyd A&CP.
 Pqq' B 32' F 39'
 Machy aft.

© 2020

Lloyd's Register
Foundation

008122-008128-0043

FOURTH DECK, amidships, Angle, E or E

thickness of Intercostal Plate