

DISCLOSED  
SECTION  
No. 588

Rpt. 8.

DISCLOSED  
SECTION  
588

(Received at London Office)

No. LON 129164A

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of LONDON

No. in Reg. Book 11390 Survey held at Date, First Survey Last Survey 19... (No. of Visits)

Supp. 9221

on the Wood, Iron or Steel SS. GIGINA

Built at NAKSHOV.

By whom AIS NAKSHOV SKIBS

When 1924. 5

TONNAGE :-  
GROSS 1222  
UNDER DK. 921  
NET 798

Owners Soc Per Angioni Navigazione e Trasporti: Owners' Address...  
(if not already recorded in Appendix to Register Book)  
Managers... Port belonging to VENICE

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...

Cell D Bor D Ba... feet; uE&B... feet; f... feet  
total capacity... tons. FPT... tons; APT... tons; MT... feet... tons.

only alterations in the existing records of tanks should be inserted.  
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 14739. Port Cpu.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form State also the dates and initials of any letters respecting this case

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS* 5.54	MBS* 4.52
SS SUB- 4.52	BLRS 5.54
	SPS 4.52
	TS OC 3.52.
Cargo bottom not fitted.	

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified } fl. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ..								

PRESENT CONDITION OF THE		Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Decks	Bulkheads	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Caulking of Decks	Ceiling	Oil Bunkers	Boats
Coamings	Cement or Asphalt	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Rudder	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Outside Plating	Steering gear and its connections	Hatches	Equipment letter
" " in way of sidelights	Windlass	Planking	Anchors, No. of
Frames	Have pumps been examined and found efficient?	Caulking	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves been examined and found efficient?	Treenails	" length mean diam. (on board.)
Longitudinals	Have Watertight Doors been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Transoms, Pointers & Crutches	Chain Locker
Floors	Air and Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Keelsons	Doubling Plates under Sounding Pipes	" " at other places	Standing and Running Rigging
Stringers		Stringers, Clamps & Shelves	Sails
Inner Bottom Plating		Salting	
Have the Tanks been examined internally?		State if examined	
Have the Tanks been tested?			

## General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1.38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Section 23)	£	:	:	19.
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.

Committee's Minute

Character Assigned

FRIDAY - 5 AUG 1933

Withdraw class  
at Owners' request

GENERAL COMMITTEE

Thursday,  
22nd September, 1933

Classing Committee's  
decision confirmed.

Surveyor to Lloyd's Register of Shipping.

024129-008136-0122

Is Certificate required? if so, to be sent to