

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

ENCLOSURE.

25th October, 1924.

Dear Sirs,

H. With reference to previous correspondence relative to the steamer "VIRGINIA DOLLAR", I enclose herewith for your information extracts from New York reports Nos. 23470 and 23956 giving details of repairs required on the hull of this vessel.


At the same time I have to inform you that the vessel will be eligible for the records of LMC-MS 4,23 B.S. 11,23 when the front end plates of the forward starboard and the two after boilers have been repaired and the port and starboard MP. cylinders and pistons and the sea connections have been examined. I may point out that the complete boiler survey will again become due at the end of next month and you will observe from the Limitation List that the limit on the wing furnaces of the forward starboard boiler is considerably overdue.

I am, Dear Sirs,
Yours faithfully,

The Surveyors,

GENOA.

Assistant to the Secretary.



P.T.O.

Lloyd's Register
Foundation

008158-002167-0242 1/2

COPY.

2. s.s. "VIRGINIA DOLLAR".

P.S:- I have also to point out that in August 1923 the Manila Surveyor recommended that repairs should be carried out to the tween deck plating at the next special survey.



© 2021

Lloyd's Register
Foundation

0242 2/2